

















8133


















8133 N


NR	ELEMENT	8133 N
E1	<div data-bbox="244 562 399 600">D8133_1N</div> <div data-bbox="443 311 537 568"></div>	1
E2	<div data-bbox="244 880 399 918">D8133_2N</div> <div data-bbox="443 647 537 904"></div>	1
E3	<div data-bbox="244 1198 399 1236">D8133_3N</div> <div data-bbox="443 960 537 1218"></div>	1
E4	<div data-bbox="244 1516 399 1554">D8133_4N</div> <div data-bbox="443 1265 537 1523"></div>	1
E5	<div data-bbox="244 1830 399 1868">D8133_5N</div> <div data-bbox="443 1597 537 1854"></div>	1
E6	<div data-bbox="244 2143 399 2181">D8133_6N</div> <div data-bbox="443 1910 537 2168"></div>	1

NR	ELEMENT	8133 N
E7		1
E8		1
E9		1
E10		1
E11		1
E12		3
E13		1



8133 N


Nr	Element			Σ
1		-	S6x60	2
2		-	W6x60	1
3		-	K2_d30_B	24
4		DIN 125	10x20	24
6		-	Z2_d30_B	24
21		DIN 125	8x16	1
56		ISO 7380	M10x30	8
57		DIN 1587	M10	12
58		-	LOCTITE	1
63		DIN 125	12x24	24
74		DIN 985	M12 (OC)	12
77		-	K3_d30_A89_G	1
79		ISO 7380	M10x40	4
213		-	Z_NA_1	1
214		-	Z_NA_2	1



8133 N

Nr	Element			Σ
229		-	Z_R_42	12
235		-	S3_8100_0	12



8133 N



8133 N



ENG: „Due to the irregular shapes of natural robinia wood trunks, all dimensions provided in the documentation may slightly vary from the actual dimensions of the product.”

PL: “Z uwagi na nieregularne kształty naturalnych pni drewna robinii, wszystkie wymiary podane w dokumentacji mogą nieznacznie odbiegać od rzeczywistych wymiarów produktu.”




1

8133 N







2

8133 N




INST_81_18_1





3

8133 N




INST_81_18_2
INST_81_162




4

8133 N



INST_81_18_3







5

8133 N

B25 0,51m³

min. 48H



6

8133 N

